			ble 5 - Summary of XRF lest Haven VA Medical Cen				
Reading No.	Floor	Location	Substrate And Component	Side	Condition	Color	Results (mg/cm ²)
1752	GROUND	G192	METAL DOOR CASING	WEST - D	INTACT	BLUE	0
1753	GROUND	G245	METAL PRIVACY PARTITION	EAST - B	Not Intact - POOR	GRAY	0.01
1754	GROUND	101	WALLBOARD WALL	SOUTH - C	INTACT	WHITE	0.01
1755	GROUND	101	METAL AIR VENT - CEILING	SOUTH - C	INTACT	WHITE	0
1756	GROUND	119	METAL ELECTRICAL BOX MOUNT	WEST - D	INTACT	GRAY	0
1757	GROUND	119	WALLBOARD WALL	WEST - D	INTACT	WHITE	0
1758	GROUND	PASSAGE 108	METAL DOOR	EAST - B	INTACT	BLACK	0
1759	GROUND	PASSAGE 108	METAL DOOR CASING	EAST - B	INTACT	BLACK	0
1761	GROUND	G187J	METAL WINDOW SASH	EAST - B	INTACT	BLACK	0
1763	GROUND	G187J	METAL WINDOW CASING	EAST - B	INTACT	BLACK	0
1764	GROUND	ELEVATOR LOBBY 1	METAL DOOR	NORTH - A	INTACT	SILVER	0.03
1765	GROUND	ELEVATOR LOBBY 1	METAL FIRE EXTINGUISHER CASING	NORTH - A	Not Intact - POOR	SILVER	1.6
1766	GROUND	ELEVATOR LOBBY 1	CONCRETE FIRE EXTINGUISHER CASING	NORTH - A	Not Intact - POOR	BLACK	0.21
1767	GROUND	ELEVATOR LOBBY 1	PLASTER WALL	NORTH - A	Not Intact - POOR	BLACK	0.21
1768	GROUND	ELEVATOR LOBBY 1	METAL PIPE	NORTH - A	Not Intact - POOR	BLACK	0.01
1769	GROUND	ELEVATOR LOBBY 1	PLASTER CEILING	NORTH - A	Not Intact - POOR	BLACK	0.28
1770	GROUND	ELEVATOR LOBBY 1	METAL HATCH	NORTH - A	Not Intact - POOR	BLACK	0
1771	GROUND	G003	METAL FIRE SPRINKLER PIPE	SOUTH - C	Not Intact - POOR	RED	0.11
1772	GROUND	G003	METAL STAIR RISER	EAST - B	Not Intact - POOR	TAN	1.7
1773	GROUND	G003	METAL STAIR STRINGER	SOUTH - C	Not Intact - POOR	TAN	3.4
1774	GROUND	G003	METAL RADIATOR COVER	NORTH - A	INTACT	WHITE	0.19
1775	GROUND	G003	CONCRETE STAIR TREAD	WEST - D	Not Intact - POOR	YELLOW	0.01
1776	GROUND	G003	CONCRETE FLOOR	WEST - D	Not Intact - POOR	RED	0.02
1777	GROUND	G003	METAL STAIR TREAD	WEST - D	Not Intact - POOR	GRAY	0.01
1778	GROUND	G003	PLASTER CEILING	NORTH - A	INTACT	WHITE	0
1779	GROUND	G003	METAL STAIR TREAD	SOUTH - C	Not Intact - POOR	BLACK	0.02
1780	GROUND	G003	METAL DOOR	EAST - B	INTACT	GRAY	0
1781	GROUND	G003	METAL AC UNIT	SOUTH - C	INTACT	TAN	0
1782	GROUND	G003	WALLBOARD WALL	NORTH - A	INTACT	WHITE	0
1783	GROUND	CORR. 3	WOOD SHELF	SOUTH - C	INTACT	WHITE	0
1784	GROUND	CORR. 3	WOOD SHELF	SOUTH - C	INTACT	WHITE	0.03

West Haven VA Medical Center, Building 1							
Reading No.	Floor	Location	Substrate And Component	Side	Condition	Color	Results (mg/cm²)
1787	GROUND	CORR. 3	CONCRETE WALL	SOUTH - C	INTACT	WHITE	0.08
1790	GROUND	CORR. 3	METAL AIR VENT - CEILING	SOUTH - C	INTACT	WHITE	0
1791	GROUND	CORR. 3	METAL DOOR CASING	EAST - B	INTACT	RED	0
1792	GROUND	CORR. 3	METAL DOOR	EAST - B	INTACT	BLUE	0
1793	GROUND	CORR. 3	METAL THRESHOLD	EAST - B	Not Intact - POOR	GRAY	3.9
1794	GROUND	CORR. 3	METAL AIR VENT - CEILING	EAST - B	INTACT	WHITE	0
1795	GROUND	G005	PLASTER CEILING	SOUTH - C	INTACT	WHITE	0
1796	GROUND	G005	METAL FIRE SPRINKLER PIPE	SOUTH - C	INTACT	RED	0.02
1797	GROUND	G005	METAL BASEBOARD	SOUTH - C	Not Intact - POOR	YELLOW	0.08
1798	GROUND	G005	CONCRETE FLOOR	SOUTH - C	Not Intact - POOR	YELLOW	0.04
1799	GROUND	G005	CONCRETE STAIR TREAD	NORTH - A	Not Intact - POOR	YELLOW	0.03
1800	GROUND	G005	METAL STAIR TREAD	NORTH - A	Not Intact - POOR	BLACK	0.03
1801	GROUND	G005	METAL STAIR RISER	NORTH - A	Not Intact - POOR	YELLOW	1.4
1802	GROUND	G005	METAL STAIR STRINGER	NORTH - A	INTACT	TAN	6.5
1803	GROUND	G114	METAL WINDOW SASH	NORTH - A	INTACT	WHITE	0
1804	GROUND	G114	WALLBOARD WALL	WEST - D	INTACT	WHITE	0.01
1806	GROUND	G114	WALLBOARD CEILING	EAST - B	INTACT	WHITE	0
1807	GROUND	G114	METAL HATCH	EAST - B	INTACT	WHITE	0
1808	GROUND	RECEPTION	WALLBOARD CEILING	EAST - B	INTACT	WHITE	0
1809	GROUND	RECEPTION	WALLBOARD WALL	NORTH - A	INTACT	WHITE	0.01
1811	GROUND	G116	WALLBOARD WALL	EAST - B	INTACT	WHITE	0
1812	GROUND	G116	WALLBOARD CEILING	EAST - B	INTACT	WHITE	0
1813	GROUND	G116	METAL HATCH	EAST - B	INTACT	WHITE	0
1814	GROUND	G116	METAL WINDOW SASH	NORTH - A	INTACT	WHITE	0
1815	GROUND	G117	METAL DOOR CASING	SOUTH - C	INTACT	BLUE	0.01
1816	GROUND	G117	METAL WINDOW SASH	NORTH - A	INTACT	WHITE	0
1817	GROUND	G117	METAL WINDOW SASH	EAST - B	INTACT	WHITE	0
1818	GROUND	G117	WALLBOARD CEILING	SOUTH - C	INTACT	WHITE	0
1819	GROUND	G117	METAL DOOR CASING	SOUTH - C	INTACT	BLUE	0.03
1820	GROUND	G153	CONCRETE FLOOR	SOUTH - C	Not Intact - POOR	GRAY	0
1821	GROUND	G153	METAL ELECTRICAL BOX MOUNT	WEST - D	INTACT	GRAY	0
1822	GROUND	G153	METAL ELECTRICAL BOX MOUNT	WEST - D	INTACT	GRAY	0
1823	GROUND	G153	METAL ELECTRICAL BOX MOUNT	EAST - B	INTACT	GRAY	0
1824	GROUND	G153	METAL BEAM	EAST - B	INTACT	GREEN	0
1827	GROUND	G153	METAL BEAM	WEST - D	INTACT	GREEN	0

			able 5 - Summary of XRF lest Haven VA Medical Cen				
Reading No.	Floor	Location	Substrate And Component	Side	Condition	Color	Results (mg/cm ²)
1828	GROUND	CORR. 3	METAL WINDOW CASING	NORTH - A	INTACT	BLUE	0
1829	GROUND	CORR. 3	METAL WINDOW CASING	NORTH - A	INTACT	BLUE	0
1830	GROUND	CORR. 4	METAL FIRE EXTINGUISHER CASING	NORTH - A	INTACT	WHITE	0
1831	GROUND	CORR. 4	WALLBOARD CEILING	NORTH - A	INTACT	WHITE	0
1832	GROUND	CORR. 4	WALLBOARD CEILING	SOUTH - C	INTACT	WHITE	0
1833	GROUND	CORR. 4	METAL HATCH	SOUTH - C	INTACT	WHITE	0
1834	GROUND	CORR. 5	METAL HATCH	WEST - D	INTACT	WHITE	0
1835	GROUND	CORR. 5	METAL AIR VENT - CEILING	NORTH - A	INTACT	WHITE	0
1836	GROUND	CORR. 5	WALLBOARD CEILING	EAST - B	INTACT	WHITE	0
1837	GROUND	CORR. 6	METAL FIRE EXTINGUISHER CASING	WEST - D	INTACT	WHITE	0
1839	GROUND	CORR. 6	METAL FIREHOSE CLOSET	WEST - D	INTACT	WHITE	0
1840	GROUND	CORR. 7	METAL FIRE EXTINGUISHER CASING	SOUTH - C	INTACT	WHITE	0
1842	GROUND	G165	WALLBOARD WALL	NORTH - A	INTACT	WHITE	0
1843	GROUND	G165	WALLBOARD WALL	SOUTH - C	INTACT	WHITE	0
1844	GROUND	G165	METAL HATCH	EAST - B	INTACT	WHITE	0
1845	GROUND	G165	LINOLEUM FLOOR	EAST - B	INTACT	BLUE	0
1846	GROUND	G140	LINOLEUM FLOOR	NORTH - A	INTACT	BLUE	0
1847	GROUND	G140	WALLBOARD WALL	NORTH - A	INTACT	WHITE	0
1848	GROUND	G140	WALLBOARD WALL	WEST - D	INTACT	WHITE	0
1849	GROUND	G140	METAL CONDUIT	NORTH - A	INTACT	WHITE	0
1850	GROUND	G140	METAL ELECTRICAL BOX MOUNT	NORTH - A	INTACT	GRAY	0
1851	GROUND	G140	WALLBOARD WALL	SOUTH - C	INTACT	WHITE	0
1852	GROUND	G140	METAL WINDOW CASING	SOUTH - C	INTACT	BLACK	0
1853	GROUND	G161	WALLBOARD CEILING	SOUTH - C	INTACT	WHITE	0
1854	GROUND	G161	METAL HATCH	SOUTH - C	INTACT	WHITE	0
1855	GROUND	G161	LINOLEUM FLOOR	SOUTH - C	INTACT	BLUE	0
1856	GROUND	CORR. 8	METAL FIRE SPRINKLER PIPE	NORTH - A	INTACT	RED	0
1857	GROUND	CORR. 8	METAL FIRE SPRINKLER PIPE	SOUTH - C	INTACT	RED	0
1858	GROUND	G249	CONCRETE FLOOR	SOUTH - C	INTACT	GRAY	0.04
1859	GROUND	CORR. 9	PLASTER CEILING	NORTH - A	INTACT	WHITE	0.07
1860	GROUND	CORR. 10	PLASTER CEILING	WEST - D	INTACT	WHITE	0.02
1861	GROUND	CORR. 10	METAL FIRE SPRINKLER PIPE	WEST - D	INTACT	RED	0.05

Table 5 - Summary of XRF Measurement	S
West Haven VA Medical Center, Building	1

West Haven VA Medical Center, Building 1							
Reading No.	Floor	Location	Substrate And Component	Side	Condition	Color	Results (mg/cm²)
1862	GROUND	CORR. 10	METAL FIRE EXTINGUISHER CASING	WEST - D	INTACT	BLUE	2.9
1863	GROUND	CORR. 10	CONCRETE FIRE EXTINGUISHER CASING	WEST - D	Not Intact - POOR	MAROON	0.05
1864	GROUND	CORR. 10	METAL PIPE	WEST - D	INTACT	RED	0.03
1865	GROUND	CORR. 10	METAL PIPE	WEST - D	INTACT	RED	0.03
1866	GROUND	CORR. 10	CONCRETE FLOOR	WEST - D	INTACT	RED	0
1870	GROUND	G250	PLASTER CEILING	WEST - D	Not Intact - POOR	WHITE	0
1871	GROUND	G250	METAL DOOR CASING	WEST - D	Not Intact - POOR	BLUE	2.8
1872	GROUND	CORR. 11	METAL CEILING	WEST - D	INTACT	WHITE	0
1873	GROUND	CORR. 11	METAL FIRE SPRINKLER PIPE	WEST - D	INTACT	RED	0.06
1874	GROUND	CORR. 12	METAL FIRE SPRINKLER PIPE	WEST - D	INTACT	RED	0.03
1875	GROUND	CORR. 12	PLASTER CEILING	WEST - D	INTACT	WHITE	0.12
1876	GROUND	CORR. 12	METAL FIRE EXTINGUISHER CASING	WEST - D	INTACT	BLUE	1.9
1877	GROUND	CORR. 12	CONCRETE FIRE EXTINGUISHER CASING	WEST - D	Not Intact - POOR	MAROON	0.04
1878	GROUND	CORR. 12	METAL PIPE	WEST - D	INTACT	BLACK	0.02
1879	GROUND	CORR. 12	METAL PIPE	WEST - D	INTACT	BLACK	0.03
1880	GROUND	CORR. 13	METAL RADIATOR COVER	WEST - D	Not Intact - POOR	WHITE	0.02
1881	GROUND	CORR. 13	CONCRETE BLOCK WALL	WEST - D	INTACT	WHITE	0
1893	GROUND	EXTERIOR	METAL WINDOW CASING	WEST - D	INTACT	BLACK	0
1894	FIRST	EXTERIOR	METAL AC UNIT	WEST - D	INTACT	GRAY	0
1895	GROUND	EXTERIOR	METAL ELECTRICAL BOX MOUNT	WEST - D	INTACT	GRAY	0
1907	GROUND	EXTERIOR	METAL BOLLARD	SOUTH - C	Not Intact - POOR	YELLOW	0
1908	GROUND	EXTERIOR	METAL BOLLARD	SOUTH - C	INTACT	YELLOW	0
1909	FIRST	EXTERIOR	METAL BOLLARD	SOUTH - C	INTACT	YELLOW	0
1910	FIRST	EXTERIOR	METAL WINDOW CASING	SOUTH - C	INTACT	BLACK	0
1911	GROUND	EXTERIOR	METAL WINDOW CASING	SOUTH - C	INTACT	BLACK	0
1912	FIRST	EXTERIOR	METAL DOOR	SOUTH - C	INTACT	BLACK	0
1915	FIRST	EXTERIOR	METAL DOOR CASING	SOUTH - C	INTACT	BLACK	0
1917	FIRST	EXTERIOR	METAL WINDOW CASING	EAST - B	INTACT	BLACK	0
1918	FIRST	EXTERIOR	METAL AC UNIT	SOUTH - C	INTACT	BEIGE	0
1919	FIRST	EXTERIOR	METAL ELECTRICAL BOX MOUNT	SOUTH - C	INTACT	GRAY	0
1920	FIRST	EXTERIOR	METAL ELECTRICAL BOX MOUNT	SOUTH - C	INTACT	GRAY	0

			ble 5 - Summary of XRF lest Haven VA Medical Cen				
Reading No.	Floor	Location	Substrate And Component	Side	Condition	Color	Results (mg/cm ²)
1921	FIRST	EXTERIOR	CONCRETE CURB	SOUTH - C	Not Intact - POOR	YELLOW	0.28
1923	FIRST	EXTERIOR	CONCRETE WALK STRIPE	SOUTH - C	Not Intact - POOR	YELLOW	0.01
1926	GROUND	EXTERIOR	METAL SIGN	SOUTH - C	Not Intact - POOR	GRAY	0.02
1927	GROUND	EXTERIOR	METAL LAMP POST	SOUTH - C	Not Intact - POOR	GRAY	0.14
1928	SUB GROUND	EXTERIOR	METAL DOOR	SOUTH - C	INTACT	BLACK	0
1929	SUB GROUND	EXTERIOR	CONCRETE WALK STRIPE	SOUTH - C	INTACT	RED	0
1930	SUB GROUND	EXTERIOR	METAL SOFFIT	SOUTH - C	INTACT	BLACK	0.01
1931	SUB GROUND	EXTERIOR	METAL DOOR	SOUTH - C	Not Intact - POOR	GRAY	0
1932	SUB GROUND	EXTERIOR	METAL DOOR CASING	SOUTH - C	Not Intact - POOR	GRAY	0.01
1933	SUB GROUND	EXTERIOR	METAL DOOR LINTEL	SOUTH - C	Not Intact - POOR	GRAY	0.03
1934	SUB GROUND	EXTERIOR	CONCRETE CURB	EAST - B	Not Intact - POOR	YELLOW	0.01
1935	SUB GROUND	EXTERIOR	ASPHALT WALK STRIPE	EAST - B	Not Intact - POOR	YELLOW	0.2
1936	SUB GROUND	EXTERIOR	METAL WINDOW CASING	EAST - B	INTACT	BLACK	0
1937	SUB GROUND	EXTERIOR	STUCCO WALL	EAST - B	INTACT	BEIGE	0
1938	SUB GROUND	EXTERIOR	METAL SPRINKLER CONNECTION	EAST - B	INTACT	RED	0.5
1939	SUB GROUND	EXTERIOR	METAL ELECTRICAL BOX MOUNT	EAST - B	INTACT	GRAY	0
1940	SUB GROUND	EXTERIOR	METAL BOLLARD	EAST - B	Not Intact - POOR	YELLOW	1.1
1941	SUB GROUND	EXTERIOR	METAL TRANSFORMER	EAST - B	INTACT	GREEN	0
1942	SUB GROUND	EXTERIOR	METAL DOOR	EAST - B	INTACT	GRAY	0
1943	SUB GROUND	EXTERIOR	METAL LAMP POST	EAST - B	Not Intact - POOR	BLACK	0.1
1945	SUB GROUND	EXTERIOR	METAL SIGN	EAST - B	INTACT	GRAY	0
1947	SUB GROUND	EXTERIOR	METAL FIRE HYDRANT	EAST - B	INTACT	RED	26.3
1949	GROUND	EXTERIOR	METAL DOOR	NORTH - A	INTACT	GRAY	0
1950	GROUND	EXTERIOR	METAL BOLLARD	NORTH - A	INTACT	YELLOW	0
1951	FIRST	EXTERIOR	METAL FIRE HYDRANT	NORTH - A	INTACT	RED	14.2
1955	GROUND	EXTERIOR	CONCRETE CURB	NORTH - A	Not Intact - POOR	YELLOW	1.7
1956	FIRST	EXTERIOR	METAL LAMP POST	NORTH - A	Not Intact - POOR	BLACK	0.2
1957	FIRST	EXTERIOR	ASPHALT WALK STRIPE	NORTH - A	Not Intact - POOR	YELLOW	0
1958	FIRST	EXTERIOR	METAL RAILING	NORTH - A	Not Intact - POOR	BLACK	0
1959	FIRST	EXTERIOR	METAL WINDOW CASING	NORTH - A	INTACT	BLACK	0

			ble 5 - Summary of XRF lest Haven VA Medical Cen				
Reading No.	Floor	Location	Substrate And Component	Side	Condition	Color	Results (mg/cm ²)
1961	FIRST	EXTERIOR	METAL LOUVER	NORTH - A	INTACT	BLACK	0
1962	GROUND	EXTERIOR	METAL DOOR	NORTH - A	INTACT	GRAY	0
1963	GROUND	EXTERIOR	METAL AC UNIT	NORTH - A	INTACT	BEIGE	0
1964	GROUND	EXTERIOR	METAL ELECTRICAL BOX MOUNT	NORTH - A	INTACT	GRAY	0
1965	GROUND	EXTERIOR	METAL RAILING	EAST - B	Not Intact - POOR	BLACK	0.08
1966	GROUND	EXTERIOR	METAL STAIR TREAD	EAST - B	INTACT	BLACK	0.02
1967	GROUND	EXTERIOR	METAL DOOR	EAST - B	Not Intact - POOR	GREEN	0.3
1968	GROUND	EXTERIOR	METAL DOOR CASING	EAST - B	Not Intact - POOR	GREEN	0
1971	GROUND	EXTERIOR	CONCRETE WALK STRIPE	EAST - B	Not Intact - POOR	RED	0.03
1972	GROUND	EXTERIOR	METAL OVERHEAD DOOR CASING	EAST - B	Not Intact - POOR	GREEN	0.26
1973	GROUND	EXTERIOR	METAL LIFT EDGE	EAST - B	Not Intact - POOR	ORANGE	0.03
1975	GROUND	EXTERIOR	METAL LOADING DOCK EDGE	EAST - B	Not Intact - POOR	RED	0
1976	GROUND	EXTERIOR	METAL CAGE	EAST - B	Not Intact - POOR	SILVER	0
1977	FIRST	EXTERIOR	METAL STAIR HANDRAIL	NORTH - A	Not Intact - POOR	BLACK	2.8
1978	FIRST	EXTERIOR	METAL STAIR STRINGER	NORTH - A	Not Intact - POOR	BLACK	4.3
1979	FIRST	EXTERIOR	METAL STAIR TREAD	NORTH - A	Not Intact - POOR	BLACK	2.8
1980	FIRST	EXTERIOR	METAL WINDOW CASING	NORTH - A	INTACT	BLACK	0
1981	FIRST	EXTERIOR	METAL AC UNIT	NORTH - A	INTACT	BEIGE	0
1982	FIRST	EXTERIOR	METAL DOOR	NORTH - A	Not Intact - POOR	GRAY	0
1983	FIRST	EXTERIOR	METAL DOOR CASING	NORTH - A	INTACT	GRAY	0.14
1985	GROUND	G 271	METAL CAGE	EAST - B	INTACT	BLACK	0
1988	GROUND	G 271	BRICK WALL	WEST - D	INTACT	ORANGE	0.01
1989	GROUND	G 271	BRICK WALL	SOUTH - C	INTACT	ORANGE	0.02
1990	GROUND	G 271	METAL CONDUIT	SOUTH - C	INTACT	BEIGE	0.01
1991	GROUND	G 271	METAL OVERHEAD DOOR	EAST - B	INTACT	GRAY	0
1992	GROUND	G 271	METAL OVERHEAD DOOR	EAST - B	INTACT	GRAY	0
1993	GROUND	G 271	METAL OVERHEAD DOOR CASING	EAST - B	INTACT	BLACK	0
1994	GROUND	G 271	METAL OVERHEAD DOOR CASING	EAST - B	INTACT	BLACK	0
1995	GROUND	G 271	METAL BOLLARD	EAST - B	Not Intact - POOR	BLACK	0.3
1996	GROUND	G 271	METAL BOLLARD	EAST - B	Not Intact - POOR	BLACK	0.17
1997	GROUND	G 271	METAL OVERHEAD DOOR	NORTH - A	INTACT	GRAY	0
1998	GROUND	G 271	METAL OVERHEAD DOOR CASING	NORTH - A	INTACT	GRAY	0

	Table 5 - Summary of XRF Measurements West Haven VA Medical Center, Building 1							
Reading No.	Floor	Location	Substrate And Component	Side	Condition	Color	Results (mg/cm ²)	
1999	SUB GROUND	SG168	PLASTER WALL	SOUTH - C	INTACT	WHITE	0.19	
2000	SUB GROUND	SG168	METAL CONDUIT	SOUTH - C	INTACT	WHITE	0	
2001	SUB GROUND	SG168	PLASTER CEILING	SOUTH - C	INTACT	WHITE	0.04	
2002	SUB GROUND	SG168	METAL FIRE SPRINKLER PIPE	SOUTH - C	INTACT	RED	0.01	
2003	SUB GROUND	SG168	METAL HATCH	SOUTH - C	INTACT	WHITE	0.06	
2004	SUB GROUND	SG168	METAL CONDUIT	SOUTH - C	INTACT	WHITE	0.02	
2005	SUB GROUND	SG168	METAL AIR VENT - CEILING	NORTH - A	INTACT	WHITE	0	
2006	SUB GROUND	SG168	METAL DOOR CASING	EAST - B	Not Intact - POOR	WHITE	3.5	
2007	SUB GROUND	CORR. 1	PLASTER WALL	SOUTH - C	Not Intact - POOR	WHITE	2.1	
2008	SUB GROUND	CORR. 1	METAL DOOR	SOUTH - C	INTACT	GRAY	0.04	
2009	SUB GROUND	CORR. 1	WOOD DOOR CASING	SOUTH - C	Not Intact - POOR	GRAY	0.08	
2010	SUB GROUND	CORR. 1	METAL FIREHOSE CLOSET	SOUTH - C	INTACT	GRAY	2.3	
2011	SUB GROUND	CORR. 1	CONCRETE FIREHOSE CLOSET	SOUTH - C	INTACT	GRAY	0.08	
2012	SUB GROUND	CORR. 1	METAL PIPE	SOUTH - C	INTACT	BLACK	0.04	
2013	SUB GROUND	CORR. 1	METAL DOOR	SOUTH - C	INTACT	GRAY	0.04	
2014	SUB GROUND	CORR. 1	METAL DOOR CASING	SOUTH - C	INTACT	GRAY	2.2	
2015	SUB GROUND	CORR. 1	PLASTER CEILING	SOUTH - C	INTACT	WHITE	0.12	
2017	SUB GROUND	CORR. 1	METAL HATCH	NORTH - A	INTACT	WHITE	0.06	
2018	SUB GROUND	CORR. 1	METAL FIRE SPRINKLER PIPE	SOUTH - C	INTACT	RED	0	
2019	SUB GROUND	CORR. 1	METAL ELECTRICAL BOX MOUNT	SOUTH - C	INTACT	GRAY	0.09	
2020	SUB GROUND	CORR. 1	METAL ELECTRICAL BOX MOUNT	SOUTH - C	INTACT	GRAY	0	
2021	SUB GROUND	SG001	PLASTER WALL	EAST - B	INTACT	WHITE	0.18	
2022	SUB GROUND	SG001	METAL CONDUIT	EAST - B	INTACT	WHITE	0	
2023	SUB GROUND	SG001	METAL DOOR CASING	NORTH - A	INTACT	GRAY	2.7	
2024	SUB GROUND	SG001	METAL FIRE SPRINKLER PIPE	NORTH - A	INTACT	RED	0.06	
2025	SUB GROUND	SG001	METAL STAIR STRINGER	EAST - B	INTACT	BEIGE	6.4	
2026	SUB GROUND	SG001	METAL RADIATOR COVER	EAST - B	INTACT	WHITE	0.14	
2027	SUB GROUND	SG001	PLASTER CEILING	SOUTH - C	INTACT	WHITE	0.13	
2028	SUB GROUND	SG021	PLASTER WALL	EAST - B	INTACT	WHITE	2.2	

			able 5 - Summary of XRF I lest Haven VA Medical Cen				
Reading No.	Floor	Location	Substrate And Component	Side	Condition	Color	Results (mg/cm ²)
2029	SUB GROUND	SG021	METAL FIREHOSE CLOSET	NORTH - A	INTACT	GRAY	3.2
2030	SUB GROUND	SG021	CONCRETE FIREHOSE CLOSET	NORTH - A	INTACT	BEIGE	0.07
2031	SUB GROUND	SG021	METAL DOOR	NORTH - A	INTACT	GRAY	0
2035	SUB GROUND	SG021	METAL DOOR CASING	NORTH - A	INTACT	GRAY	1.5
2036	SUB GROUND	SG021	METAL FIRE SPRINKLER PIPE	NORTH - A	INTACT	RED	0
2037	SUB GROUND	SG002	METAL STAIR TREAD	SOUTH - C	INTACT	BLACK	0.08
2038	SUB GROUND	SG002	CONCRETE STAIR TREAD	SOUTH - C	INTACT	BEIGE	0.03
2039	SUB GROUND	SG002	METAL STAIR RISER	SOUTH - C	INTACT	GREEN	1.6
2040	SUB GROUND	SG002	PLASTER WALL	WEST - D	INTACT	WHITE	0.24
2041	SUB GROUND	SG002	CONCRETE FLOOR	SOUTH - C	Not Intact - POOR	YELLOW	0.05
2042	SUB GROUND	SG002	METAL BASEBOARD	SOUTH - C	INTACT	GRAY	3.7
2043	SUB GROUND	SG002	METAL RADIATOR COVER	WEST - D	INTACT	WHITE	0.25
2044	SUB GROUND	SG002	METAL FIRE SPRINKLER PIPE	NORTH - A	INTACT	RED	0.26
2045	SUB GROUND	SG002	METAL DOOR CASING	NORTH - A	INTACT	RED	2.4
2046	SUB GROUND	SG139	PLASTER WALL	SOUTH - C	INTACT	GREEN	0
2047	SUB GROUND	SG130	WALLBOARD WALL	SOUTH - C	INTACT	WHITE	0
2048	SUB GROUND	SG130	WALLBOARD WALL	EAST - B	INTACT	WHITE	0
2051	SUB GROUND	SG130	WALLBOARD WALL	NORTH - A	INTACT	WHITE	0
2052	SUB GROUND	SG130	WALLBOARD WALL	WEST - D	INTACT	WHITE	0
2055	SUB GROUND	SG129	CONCRETE BLOCK WALL	NORTH - A	INTACT	WHITE	0
2057	SUB GROUND	SG129	CONCRETE BLOCK WALL	WEST - D	INTACT	WHITE	1.6
2058	SUB GROUND	SG129	CONCRETE BLOCK WALL	SOUTH - C	INTACT	WHITE	0
2059	SUB GROUND	SG129	CONCRETE BLOCK WALL	EAST - B	INTACT	WHITE	0.01
2060	SUB GROUND	SG129	METAL ELECTRICAL BOX MOUNT	NORTH - A	INTACT	GRAY	0
2062	SUB GROUND	SG129	METAL FIRE SPRINKLER PIPE	NORTH - A	INTACT	RED	0
2063	SUB GROUND	SG129	METAL CONDUIT	NORTH - A	INTACT	WHITE	0
2064	SUB GROUND	SG129	METAL ELECTRICAL BOX MOUNT	SOUTH - C	INTACT	GRAY	0
2065	SUB GROUND	SG139	METAL RADIATOR COVER	SOUTH - C	INTACT	GRAY	0.03
2066	SUB GROUND	SG139	METAL DOOR	EAST - B	INTACT	GRAY	0

			able 5 - Summary of XRF lest Haven VA Medical Cen				
Reading No.	Floor	Location	Substrate And Component	Side	Condition	Color	Results (mg/cm²)
2067	SUB GROUND	SG139	METAL DOOR CASING	EAST - B	INTACT	GRAY	0
2068	SUB GROUND	SG139	METAL RADIATOR COVER	EAST - B	INTACT	WHITE	0.1
2069	SUB GROUND	SG139	METAL WINDOW CASING	EAST - B	INTACT	WHITE	0.01
2070	SUB GROUND	SG139	METAL HATCH	SOUTH - C	INTACT	WHITE	0
2071	SUB GROUND	SG139	METAL WINDOW SASH	EAST - B	INTACT	BLACK	0
2072	SUB GROUND	SG139	SLATE WINDOW SILL	EAST - B	INTACT	WHITE	0
2073	SUB GROUND	SG111	WALLBOARD WALL	NORTH - A	INTACT	ORANGE	0
2074	SUB GROUND	SG111	WALLBOARD WALL	EAST - B	INTACT	ORANGE	0
2075	SUB GROUND	SG111	METAL WINDOW CASING	SOUTH - C	INTACT	GRAY	0
2076	SUB GROUND	SG111	METAL DOOR CASING	SOUTH - C	INTACT	GRAY	0
2077	SUB GROUND	SG0114	WALLBOARD WALL	EAST - B	INTACT	ORANGE	0
2078	SUB GROUND	SG0114	WALLBOARD WALL	SOUTH - C	INTACT	ORANGE	7.8
2080	SUB GROUND	SG114B	WALLBOARD WALL	NORTH - A	INTACT	BEIGE	5.3
2081	SUB GROUND	SG129	WALLBOARD WALL	NORTH - A	INTACT	BEIGE	5.4
2082	SUB GROUND	SG129	METAL WINDOW CASING	EAST - B	INTACT	GRAY	10.1
2083	SUB GROUND	SG1114B	LINOLEUM FLOOR	EAST - B	INTACT	BROWN	0
2084	SUB GROUND	SG121	METAL DOOR	NORTH - A	INTACT	ORANGE	0
2085	SUB GROUND	SG121	METAL AIR VENT - CEILING	NORTH - A	INTACT	WHITE	- 0.23
2086	SUB GROUND	STAIR 5	METAL STAIR TREAD	NORTH - A	INTACT	YELLOW	0.02
2087	SUB GROUND	STAIR 5	METAL STAIR TREAD	NORTH - A	INTACT	BLACK	0.02
2088	SUB GROUND	STAIR 5	METAL STAIR RISER	NORTH - A	INTACT	YELLOW	1.5
2089	SUB GROUND	STAIR 5	METAL BASEBOARD	NORTH - A	INTACT	YELLOW	2.2
2090	SUB GROUND	STAIR 5	METAL STAIR STRINGER	WEST - D	INTACT	TAN	3.2
2091	SUB GROUND	STAIR 5	METAL FIRE SPRINKLER PIPE	SOUTH - C	INTACT	RED	0.05
2092	SUB GROUND	STAIR 5	PLASTER WALL	SOUTH - C	INTACT	WHITE	0.21
2093	SUB GROUND	STAIR 5	CONCRETE FLOOR	SOUTH - C	INTACT	YELLOW	0.05
2094	SUB GROUND	STAIR 5	METAL DOOR CASING	SOUTH - C	INTACT	RED	3.6
2095	SUB GROUND	SG024	METAL ELEVATOR DOOR	EAST - B	INTACT	GRAY	0.27

Table 5 - Summary of XRF Measureme	nts
West Haven VA Medical Center, Buildin	g 1

West Haven VA Medical Center, Building 1							
Reading No.	Floor	Location	Substrate And Component	Side	Condition	Color	Results (mg/cm²)
2096	SUB GROUND	SG024	METAL ELEVATOR DOOR CASING	EAST - B	INTACT	GRAY	0.22
2098	SUB GROUND	SG024	PLASTER WALL	SOUTH - C	INTACT	WHITE	2.7
2099	SUB GROUND	SG024	METAL ELECTRICAL BOX MOUNT	NORTH - A	INTACT	GRAY	0
2100	SUB GROUND	SG024	METAL FIRE SPRINKLER PIPE	NORTH - A	INTACT	RED	0
2110	SUB GROUND	CORR. 2	WALLBOARD WALL	NORTH - A	INTACT	BEIGE	0
2111	SUB GROUND	CORR. 2	METAL DOOR CASING	SOUTH - C	INTACT	WHITE	0
2112	SUB GROUND	CORR. 2	METAL AIR VENT - CEILING	EAST - B	INTACT	WHITE	0
2113	SUB GROUND	CORR. 2	METAL AIR VENT - CEILING	EAST - B	INTACT	WHITE	0.01
2114	SUB GROUND	CORR. 2	AIR VENT - CEILING	EAST - B	INTACT	WHITE	0
2115	SUB GROUND	CORR. 3	WALLBOARD WALL	EAST - B	INTACT	BEIGE	0
2116	SUB GROUND	CORR. 3	METAL FIRE EXTINGUISHER CASING	SOUTH - C	INTACT	WHITE	0
2117	SUB GROUND	CORR. 3	METAL DOOR	SOUTH - C	INTACT	WHITE	0
2118	SUB GROUND	CORR. 3	METAL AIR VENT - CEILING	EAST - B	INTACT	WHITE	0
2119	SUB GROUND	CORR. 3	METAL DOOR	EAST - B	Not Intact- POOR	WHITE	0
2120	SUB GROUND	CORR. 3	METALFIRE EXTINGUISHER CASING	NORTH - A	INTACT	WHITE	0
2121	SUB GROUND	CORR. 3	METAL HATCH	NORTH - A	INTACT	BEIGE	0.07
2122	SUB GROUND	CORR. 3	METAL ELECTRICAL BOX MOUNT	EAST - B	INTACT	GRAY	0
2123	SUB GROUND	STAIR 9	CONCRETE BLOCK WALL	WEST - D	INTACT	YELLOW	0
2124	SUB GROUND	STAIR 9	CONCRETE BLOCK WALL	NORTH - A	INTACT	YELLOW	0
2125	SUB GROUND	STAIR 9	CONCRETE BLOCK WALL	EAST - B	INTACT	YELLOW	0.01
2126	SUB GROUND	STAIR 9	WALLBOARD CEILING	NORTH - A	INTACT	YELLOW	0
2127	SUB GROUND	STAIR 9	WALLBOARD CEILING	NORTH - A	INTACT	YELLOW	0
2128	SUB GROUND	STAIR 9	WALLBOARD CEILING	NORTH - A	INTACT	YELLOW	0
2129	SUB GROUND	STAIR 9	CONCRETE WALL	NORTH - A	INTACT	WHITE	0
2130	SUB GROUND	STAIR 9	METAL DOOR LINTEL	EAST - B	INTACT	YELLOW	0.07
2131	SUB GROUND	STAIR 9	METAL FIRE SPRINKLER PIPE	EAST - B	Not Intact- POOR	BLACK	0
2132	SUB GROUND	STAIR 9	METAL STAIR STRINGER	EAST - B	Not Intact- POOR	YELLOW	0.02
2133	SUB GROUND	STAIR 9	METAL STAIR NEWEL POST	EAST - B	Not Intact- POOR	YELLOW	0.02

Table 5 - Summary of XRF Measurements West Haven VA Medical Center, Building 1							
Reading No.	Floor	Location	Substrate And Component	Side	Condition	Color	Results (mg/cm ²)
2134	SUB GROUND	STAIR 9	METAL STAIR BALUSTER	EAST - B	Not Intact- POOR	YELLOW	0
2135	SUB GROUND	STAIR 9	METAL STAIR BALUSTER	EAST - B	Not Intact- POOR	YELLOW	0.04
2136	SUB GROUND	STAIR 9	METAL RADIATOR	SOUTH - C	Not Intact- POOR	YELLOW	0.01
2137	SUB GROUND	CORR. 4	METAL FIRE EXTINGUISHER CASING	WEST - D	INTACT	WHITE	0
2138	SUB GROUND	CORR. 4	METAL AIR VENT - CEILING	SOUTH - C	INTACT	WHITE	0
2139	SUB GROUND	CORR. 4	METAL CONDUIT	SOUTH - C	INTACT	BEIGE	0
2140	SUB GROUND	SG026	METAL CONDUIT	SOUTH - C	INTACT	WHITE	0
2141	SUB GROUND	SG026	METAL CONDUIT	SOUTH - C	INTACT	WHITE	0.05
2142	SUB GROUND	SG026	METAL FAN	NORTH - A	INTACT	TAN	0
2143	SUB GROUND	SG107	METAL PRIVACY PARTITION	SOUTH - C	Not Intact- POOR	TAN	0.11
2144	SUB GROUND	SG107	METAL PRIVACY PARTITION	SOUTH - C	Not Intact- POOR	TAN	0.02
2145	SUB GROUND	SG107	PLASTER CEILING	SOUTH - C	INTACT	WHITE	0.05
2146	SUB GROUND	SG109	PLASTER CEILING	NORTH - A	Not Intact- POOR	WHITE	0.05
2147	SUB GROUND	SG109	METAL PRIVACY PARTITION	SOUTH - C	Not Intact- POOR	TAN	0.06
2148	SUB GROUND	SG109	METAL PIPE	SOUTH - C	Not Intact- POOR	TAN	0.7
2149	SUB GROUND	SG109	METAL HATCH	SOUTH - C	INTACT	WHITE	0.03
2150	SUB GROUND	SG109	METAL HATCH	NORTH - A	INTACT	WHITE	0.11
2151	SUB GROUND	SG109	METAL HATCH	NORTH - A	INTACT	WHITE	0.06
2152	SUB GROUND	EXTERIOR LOADING DOCK	METAL COLUMN	NORTH - A	Not Intact- POOR	WHITE	0
2153	SUB GROUND	EXTERIOR LOADING DOCK	METAL COLUMN	SOUTH - C	Not Intact- POOR	WHITE	0
2154	SUB GROUND	EXTERIOR LOADING DOCK	METAL STAIR HANDRAIL	SOUTH - C	Not Intact- POOR	BLACK	9.5
2155	SUB GROUND	EXTERIOR LOADING DOCK	METAL WINDOW CASING	NORTH - A	INTACT	BLACK	0
2156	SUB GROUND	EXTERIOR LOADING DOCK	METAL WINDOW CASING	NORTH - A	INTACT	BLACK	0
2157	SUB GROUND	EXTERIOR LOADING DOCK	METAL LIFT RAILING	NORTH - A	Not Intact- POOR	YELLOW	0.01
2158	SUB GROUND	EXTERIOR LOADING DOCK	METAL LIFT	NORTH - A	Not Intact- POOR	YELLOW	0.01

Table 5 - Summary of XRF Measurements West Haven VA Medical Center, Building 1							
Reading No.	Floor	Location	Substrate And Component	Side	Condition	Color	Results (mg/cm²)
2159	SUB GROUND	EXTERIOR LOADING DOCK	CONCRETE WALK STRIPE	NORTH - A	Not Intact- POOR	RED	0
2160	SUB GROUND	CORR. 5	METAL WINDOW CASING	EAST - B	INTACT	BLACK	0
2161	SUB GROUND	CORR. 5	METAL WINDOW CASING	EAST - B	INTACT	BLACK	0
2162	SUB GROUND	CORR. 5	METAL WINDOW SASH	EAST - B	INTACT	BLACK	0
2163	SUB GROUND	CORR. 5	METAL WINDOW SASH	EAST - B	INTACT	BLACK	0.01
2164	SUB GROUND	SG105	METAL ELECTRICAL BOX MOUNT	EAST - B	INTACT	TAN	0
2165	SUB GROUND	SG105	METAL ELECTRICAL BOX MOUNT	EAST - B	INTACT	TAN	0
2166	SUB GROUND	SG180a	CONCRETE WALL	SOUTH - C	Not Intact- POOR	GREEN	0.11
2167	SUB GROUND	SG180a	METAL ELECTRICAL BOX MOUNT	SOUTH - C	INTACT	GRAY	0
2168	SUB GROUND	SG168	CONCRETE COLUMN	WEST - D	INTACT	GREEN	0.04
2169	SUB GROUND	SG168	CONCRETE COLUMN	WEST - D	INTACT	GREEN	0
2170	SUB GROUND	SG168	CONCRETE COLUMN	WEST - D	INTACT	GREEN	0
2171	SUB GROUND	SG168	CONCRETE COLUMN	WEST - D	INTACT	GREEN	0.04
2172	SUB GROUND	SG168	WALLBOARD WALL	WEST - D	Not Intact- POOR	GREEN	0.01
2173	SUB GROUND	SG168	WOOD STAIR HANDRAIL	WEST - D	Not Intact- POOR	GRAY	0.02
2174	SUB GROUND	SG168	WOOD STAIR STRINGER	WEST - D	Not Intact- POOR	GRAY	0.03
2175	SUB GROUND	SG168	WOOD STAIR TREAD	WEST - D	Not Intact- POOR	GRAY	0.07
2176	SUB GROUND	SG1800	METAL PIPE	WEST - D	INTACT	RED	0.06
2177	SUB GROUND	SG1800	METAL STAIR HANDRAIL	SOUTH - C	INTACT	RED	0.01
2178	SUB GROUND	SG1800	METAL STAIR STRINGER	SOUTH - C	INTACT	RED	0
2179	SUB GROUND	SG1800	METAL STAIR TREAD	SOUTH - C	INTACT	RED	0
2180	SUB GROUND	SG182	CEREAMIC BLOCK WALL	SOUTH - C	Not Intact- POOR	GREEN	0.03
2181	SUB GROUND	SG182	CEREAMIC BLOCK WALL	WEST - D	Not Intact- POOR	GREEN	0.09
2182	SUB GROUND	SG182	CEREAMIC BLOCK WALL	WEST - D	Not Intact- POOR	GREEN	0.05
2183	SUB GROUND	SG182	CEREAMIC BLOCK WALL	WEST - D	Not Intact- POOR	GREEN	0.03
2184	SUB GROUND	SG182	CONCRETE 'WALL	NORTH - A	Not Intact- POOR	GREEN	0.05

Table 5 - Summary of XRF Measurements West Haven VA Medical Center, Building 1							
Reading No.	Floor	Location	Substrate And Component	Side	Condition	Color	Results (mg/cm²)
2185	SUB GROUND	SG182	METAL CONDUIT	NORTH - A	INTACT	GREEN	0
2186	SUB GROUND	SG182	CONCRETE COLUMN	NORTH - A	Not Intact- POOR	GREEN	0.06
2187	SUB GROUND	SG182	CONCRETE COLUMN	NORTH - A	Not Intact- POOR	GREEN	0.04
2188	SUB GROUND	SG182	CONCRETE COLUMN	SOUTH - C	Not Intact- POOR	GREEN	0.09
2189	SUB GROUND	SG182	CONCRETE COLUMN	SOUTH - C	Not Intact- POOR	GREEN	0.07
2190	SUB GROUND	SG182	CONCRETE COLUMN	SOUTH - C	Not Intact- POOR	GREEN	0.03
2191	SUB GROUND	SG182	CONCRETE COLUMN	SOUTH - C	Not Intact- POOR	GREEN	0.05
2192	SUB GROUND	SG182	CONCRETE COLUMN	SOUTH - C	Not Intact- POOR	GREEN	0.07
2193	SUB GROUND	SMALLER STAIR BY STAIR 9	METAL LADDER	SOUTH - C	Not Intact- POOR	BLACK	0.03

Font Color Annotation:

Black - Below the VISN 1 Threshold of 0.1 mg/cm²
- Above the VISN 1 Threshold of 0.1 mg/cm², but less than 1.0 mg/cm²
- Greater than 1.0 mg/cm²

Appendix C

Representative Photographs of ACM



Pipe Elbow Mudded Sample SSG - 7A



Air Cell Pipe Insulation Sample SSG-14A




Glue w/12"x12" Cream Vinyl Floor Tile w/Gray Streaks Sample SSG – 18A



Mastic w/12"x12" Cream Vinyl Floor Tile w/Tan Specks Sample SG - 2A



Mastic w/12"x12" Light Green Vinyl Floor Tile w/Gray Specks Sample SG - 16A



Mastic w/6" Dark Brown Cove Base Sample SG - 18A



Window Caulk Sample G - 19A



Glue for 12"x12" Cream Floor Tile Sample G - 33A



9X9" White Vinyl Floor Tile w /White Specks Sample G - 42A



9X9" Red Vinyl Floor Tile Sample G-57A



12"x12" Brown Mottled Vinyl Floor Tile Sample G–59A




Glue for 12"x12" Brown Mottled Vinyl Floor Tile Sample G - 60A




Pipe Insulation Sample G - 63A



Pipe Joint Insulation Sample G - 64A



Exposed Glue Daubs on Duct Sample G - 65A



9"x9" Green Vinyl Floor Tile w/Gray Specks (below carpet) Sample 1 - 1A



9"x9" Light Brown Vinyl Floor Tile w/Black Streaks (below carpet) Sample 1 - 34A



9"X9" Gray Vinyl Floor Tile w/White Specks Sample 1 - 37A



9"x9" Dark Brown Vinyl Floor Tile Sample 1 - 40A



Mastic w/12"x12" Brown Vinyl Floor Tile w/Brown Streaks Sample 1 - 43A



Mastic w/12"x12" Blue Vinyl Floor Tile w/White Streaks Sample 1 - 45A



Mastic w/12"x12" Brown Marble Vinyl Floor Tile Sample 1 - 47A



Pipe Insulation, Air Cell Sample 1 - 48A



Sink Undercoating Black Sample 1 - 57A



12"x12" Gray Vinyl Floor Tile w/Gray Specks (below carpet) Sample 1 - 68A



9"x9" Black Vinyl Floor Tile (below carpet) Sample 1 - 70A



Mastic w/9"x9" Black Vinyl Floor Tile (below carpet) Sample 1 - 71A



Mastic w/12"x12" Light Brown Vinyl Floor Tile w/Dark Brown Specks Sample 1 - 73A




12"X12" Tan Vinyl Floor Tile Stone Pattern Sample 1 - 74A



Mastic w/12"x12" Tan Vinyl Floor Tile Stone Pattern Sample 1 - 75A



9"x9" Dark Green Vinyl Floor Tile and Mastic Samples 2 - 11A & 2 - 12A




9"x9" Green Vinyl Floor Tile w/Gray Specks (below carpet) Sample 2 - 19A



9"x9" Red Vinyl Floor Tile w/White Specks Sample 2 - 24A



Mastic w/9"x9" Red Vinyl Floor Tile w/White Specks Sample 2 - 25B



Transite Wall Panel w/Pinholes Sample 2 - 41A



Transite Heat Panel Sample 2 - 51A



Pipe Elbow Insulation Sample 3 - 22A



Pipe End Cap Insulation Sample 3 - 23A




9"x9" Light Green Vinyl Floor Tile w/Gray Specks Sample 4 - 6A



Mastic w/9"x9" Light Green Vinyl Floor Tile w/Gray Specks Sample 4 - 7A



9"x9" Red Vinyl Floor Tile (under exposed white vinyl floor tile) Sample 4 - 17A



12"x12" Cream Vinyl Floor Tile w/Brown Streaks Sample 4 - 21B




9"x9" Light Brown Vinyl Floor Tile w/Dark Brown Streaks Sample 4 - 30A



9"x9" Dark Green Vinyl Floor Tile Sample 4 - 52A



9"x9" Light Gray Vinyl Floor Tile (below carpet) Sample 4 - 54A




Mastic w/12"x12" Cream Vinyl Floor Tile w/Gray Specks Sample 5 - 29A




Sink Undercoating Black Sample 6 - 11A



Glue Daubs on Ducts Sample 6 - 17A



9"x9" Dark Brown Vinyl Floor Tile w/White Streaks (Below Carpet) Sample 6 - 26A



Mastic w/9"x9" Dark Brown Vinyl Floor Tile w/White Streaks (below carpet)
Sample 6 - 27A



9"x9" Green Vinyl Floor Tile w/White Streaks Sample 6 - 30A




9"x9" Light Brown Vinyl Floor Tile w/Black Streaks Sample 7 - 5A



Mastic w/9"x9" Light Brown Vinyl Floor Tile w/Black Streaks Sample 7 - 6A



9"x9" Dark Green Vinyl Floor Ceiling Tile w/White Streaks Sample 7 - 7A



Glue w/Blue Carpet Sample 7 - 11A



9"x9" Brown Floor Tile w/White & Dark Brown Streaks Sample 7-14B



Mastic w/9"x9" Brown Floor Tile w/White & Dark Brown Streaks Sample 7 - 15A



Dark Brown Flooring Border Sample 7 - 28A



Black Flooring Along Border Sample 7 - 29A



Yellow Linoleum w/Gold Spots Sample 7 - 38A




Mastic w/Yellow Linoleum w/Gold Spots Sample 7 - 39A



Glue w/Pink Carpet Sample 7 - 40A



9"x9" Green Vinyl Floor Tile w/White Sample 8 - 15A



Black Border Vinyl Floor Tile Sample 8 - 17A



Sink Undercoating Thick Black Sample 8 - 22A



9"x9" Light Brown Vinyl Acrylic Tile with Streaks Sample 9 – 20A



Dark Brown Boarder Vinyl Acrylic Tile Sample 9 - 24A



12"x12" Cream Vinyl Floor Tiles w Tan Specks Sample 9 - 25A



9"x9"' Gray Vinyl Acrylic Tile w Black Streaks Sample 9 - 27A



Mastic Under 9' Gray Vinyl Acrylic Tile w Black Streaks Sample 9 - 28A



Black Boarder Vinyl Acrylic Tile Sample 9 - 29A



12"x12" Cream Vinyl Floor Tiles w Tan Specks Sample 9 - 31A



9"x9" Green Vinyl Floor Tile (below carpet) Sample 9 - 42A



Water Tank Insulation Sample Penthouse - 12A



Pipe Insulation Sample AC - 6 - 5A




Pipe Fittings Sample AC - G - 8A



Black Wall Mastic Sample AC - SG - 10A



Louver Hard White Caulk Sample E - 4A



Expansion Joint Hard White Sample E - 8A




Door Frame White Caulk Sample E - 1A

Appendix D

Representative Photographs of Non-Intact Lead Containing Paint Greater than or Equal to 1.0 mg/cm



Metal Ladder Sample 9



Metal Hatch Casing Sample 17



Metal Door Lintel Sample 57



Metal Door Casing Sample 69




Metal Threshold Sample 86




Metal Stair Riser Sample 94




Metal Stair Handrail Sample 97



Metal Newel Post Sample 98



Metal Stair Stringer Sample 105




Metal Stair Baseboard Sample 133



Metal Hatch Sample 134



Metal Gate Door Sample 135



Metal Gate Sample 136




Metal Trim Sample 137



Metal Pipe Sample 327



Plaster Wall Sample 448



Metal Wall Sample 546



Concrete Floor Sample 751



Concrete Wall Sample 1051



Metal Window Casing Sample 1091



Metal Fire Extinguisher Casing Sample 1765



Metal Bollard Exterior Sample 1940



Concrete Curb Exterior Sample1955



Metal Stair Handrail Exterior Sample 1977



Metal Stair Stringer Exterior Sample 1978



Metal Stair Tread Exterior Sample 1979



Regards,

Marianne Mason <marianne.mason@nara.gov>

Fwd: Notification and Request to Destroy Records (Medical X-Rays) Darin Cote <darin.cote@nara.gov> Wed, Jul 28, 2021 at 3:02 PM To: Marianne Mason <marianne.mason@nara.gov> Cc: Jack Kabrel <jack.kabrel@nara.gov> Hi all, We have another FRED case for review. I couldn't recall who was next in the memo response coordinator queue. But after some digging.....Anne, you win! See email notes from VA and David Weber below. I've asked David if he wants to be co:ed on correspondence. Will let you know. Best, Darin Coté Electronic Records Policy Analyst Policy and Program Support Team (ACPP) Office of the Chief Records Officer for the U.S. Government. National Archives and Records Administration w 817,551,2003 c Forwarded message From: David Weber < david weber@nara.gov> Date: Wed, Jul 28, 2021 at 1:52 PM Subject: Fwd: Notification and Request to Destroy Records (Medical X-Rays) To Darin Cote <darin cote@nara gov> Here's what RM sent me. Matt had already told me about it and we've talked about ways to help make it less likely in the future. Forwarded message From: RM Communications <m.communications@nara.gov> Date: Wed, Jul 28, 2021 at 7:23 AM Subject: Fwd: Notification and Request to Destroy Records (Medical X-Rays) To: David Weber < david weber@nara.gov> Please respond to this inquiry from rded message via RM Communications <rm.communications@nara.gov> From Date: Tue, Jul 27, 2021 at 4:19 PM Subject: Notification and Request to Destroy Records (Medical X-Rays) To: rm.communications@nara.gov <rm.communications@nara.gov> Cc; david weber@nara.gov <david.weber@nara.gov> @va.gov? ava.gov> @va.gov> Greetings NARA Representatives, and representing the VA SAORM, I concur with the Veterans Health Administration's assessment that the subject records (deemed as contaminated) need to be destroyed per, 44 USC 3310 and 36 CFR 1229.10. The subject records (X-rays) pose a continuing menace to human health, life, and property. The records are in a room with asbestos. To separate them as active vs. inactive will require someone to touch each film and be exposed to mold and asbestos. Date range of Damaged X-rays: 2003 and prior Shelved Feet of X-rays: 83 ft (Approximately 30,000 X-rays) Contamination: Asbestos and Mold Proposed disposal plan for Contaminated X-rays: Contract being prepared to address the remediation of the mold and asbestos contamination Please notify the individuals included in the email of NARA's decision.

https://mail.google.com/mail/u/0?ik=75e54755f4&view=pt&search=all&perm(hid=thread-f%3A1706556381499566673&simpl=msg-f%3A17065563814... 1/11

2 attachments

Report on Accidental Destruction of Medical X-rays VA Connecticut.pdf 132K

VA damage records VA West Haven medical center.pdf 148K

Anne Mason <marianne,mason@nara.gov>

To: Darin Cole <darin.cole@nara.gov> Cc: Jack Kabrel <jack.kabrel@nara.gov>

Lucky met Shall I schedule a meeting for the three of us to discuss prior to contacting VA? I think we need some more into before we write our memo to R so, I'll need to contact VA.

[Quoted text hidden]

Anne Mason (she/her), CA Office of the Chief Records Officer, Operations Research and Support Team Archives Specialist 301-837-3502 marianne.mason@nara.gov

Darin Cote <darin.cote@nara.gov>

To: Anne Mason <marianne.mason@nara.gov> Cc: Jack Kabrel <jack.kabrel@nara.gov>

Wed, Jul 28, 2021 at 3:19 PM

Wed. Jul 28, 2021 at 3:17 PM

Yes, please do. It's been so long between cases, I'm sure muscle memory is gone here.

Darin Coté Electronic Records Policy Analyst Policy and Program Support Team (ACPP) Office of the Chief Records Officer for the U.S. Government National Archives and Records Administration w 817.551.2003 c (b) (6)



[Quoted text hidden]

Jack Kabrel <jack kabrel@nara.gov>

To: Darin Cote <darin.cote@nara.gov>

Cc: Anne Mason <marianne.mason@nara.gov>

Wed. Jul 28, 2021 at 3:21 PM

LOL, yeah where do we begin again.

In all fairness Anne, I will try to assist you on this as much as I can. I'll look at past emails and try to come up w/ a process or checklist that we can use.

Yeah setting up a date is fine when we are all free.

Jack

Jack Kabrel

Jack.Kabrel@nara.gov

Archives Specialist

National Archives and Records Administration

Permanent Records Capture Section

Cell (

[Quoted text hidden]

Darin Cote <darin.cote@nara.gov> To: Jack Kabrel < jack kabrel@nara.gov> Cc: Anne Mason <marianne.mason@nara.gov> Wed, Jul 28, 2021 at 3:26 PM

Anne.

23-00001-C 315 of 338

National Archives & Records Administration Mail - Fwd: Notification and Request to Destroy Records (Medical X-Rays)

I created a pdf of the original email from VA to David Weber and dropped it into the FY2	1 case file I created called VA_CT
Best,	
Darin Coté Electronic Records Policy Analyst Policy and Program Support Team (ACPP) Office of the Chief Records Officer for the U.S. Government National Archives and Records Administration w 817.551.2003 c	
NATURAL ARCHIVAL	
[Quoted text hidden]	
Anne Mason <marianne,mason@nara.gov> To: Darin Cote <darin.cote@nara.gov> Cc: Jack Kabrel <jack.kabrel@nara.gov> Thanks Darin. I dropped in the 2 attachments to the VA email</jack.kabrel@nara.gov></darin.cote@nara.gov></marianne,mason@nara.gov>	Wed, Jul 28, 2021 at 3:40 PM
[Quoted text hidden]	
Anne Mason <marianne,mason@nara.gov> To Representation To Representat</marianne,mason@nara.gov>	Tue, Aug 3, 2021 at 9:01 AM
Cc: Jack Kabrel <jack,kabrel@nara.gov> Darin Cote <darin.cote@nara.gov>, Pamela Na <david.weber@nara.gov> @va.gov @va.gov @va.gov</david.weber@nara.gov></darin.cote@nara.gov></jack,kabrel@nara.gov>	<u>jar-Simpson <pamela.najar-simpson@nara.gov></pamela.najar-simpson@nara.gov></u> David Weber gva.gov
Hejlo ole	
Thank you for the information about this emergency disposal request. I've been assigned questions.	d to this case. As NARA considers this request, I have a few
 Have these records already been destroyed? One of the attachments talked abordamaged rather than destroyed, but I wanted to confirm that the records are still 2. Has the storage area and air been tested for asbestos? If so, could we get a cop 3, Do you have any photographs that would show the mold and other contamination 4. David Weber provided me with the NARA records scredule citation, N1-15-87-4, the x-rays into the EHR started? If the analysis/report was done on paper, was to 5. You mentioned that a contract was in progress for remediation. Are there plans for the contract was in progress. 	extant. y of that report? to of the records? Item 13a. Do you know when the practice of entering the analysis of that put in the patients' file or was it interfiled with these x-rays?
Once we have all the information we need, we will make a recommendation to the Arch Officer, Laurence Brewer. In the meantime, please let me know if you have any question	
Anne Mason (she/her), CA Office of the Chief Records Officer, Operations Research and Support Team Archives Specialist 301-837-3502 (office)	
Jesosian revi ulombuli	
©va.gov> To: Anne Mason <marianne,mason@nara.gov> @va.gov></marianne,mason@nara.gov>	Tue, Aug 3, 2021 at 9;27 AM
Cc: Jack Kabrel < jack kabrel@nara.gov>. Darin Cote < darin.cote@nara.gov>. Pamela Nacquid weber@nara.gov> @va.gov> @va.gov> @va.gov>. @	ojar-Simpson <pamela.najar-simpson@nara.gov> David Weber @va.gov> @va.gov></pamela.najar-simpson@nara.gov>
Ms; Mason,	
Good Morning!	
I will be able to provide you with the below information (Questions 2.3 and 4) but will no with the report from our Safety/Environmental folks. I am not sure of the turn around on	
The answers to 1 and 5 are;	

National Archives & Records Administration Mail - Fwd: Notification and Request to Destroy Records (Medical X-Rays)

No, the X-rays have not been destroyed and we are waiting NARA's approval before we begin the contracting process and yes the disposition/remediation will be part of the contract.

Thank you,	
(2)(-5)	
Very Respectfully,	
(5)(6)	
555 Willard Ave Newington, CT 06111	J
Station #689 Office 1-414	
Records Room B127-2E	
P: 860-666-6951 Ext	
Cell: DI(S)	
(b)(6) Dva.gov	
@va.gov	
[Quoted text hidden]	
Anne Mason <marianne.mason@nara.gov> To: Description: Description: Description: Description: Anne Mason <marianne.mason@nara.gov> Description: Descrip</marianne.mason@nara.gov></marianne.mason@nara.gov>	Tue, Aug 3, 2021 at 9:38 AM
Thank you for the quick response!	
[Quoted text hidden] Anne Mason (she/her), CA	
[Quoted text hidden] marianne.mason@nara.gov	
Anne Mason <marianne.mason@nara.gov></marianne.mason@nara.gov>	Tue, Aug 3, 2021 at 10:37 AN
To: Jack Kabrel < jack.kabrel@nara.gov > Cc: Darin Cote < darin.cote@nara.gov > , Pamela Najar-Simpson < pamela.najar-sim	pson@nara.gov>, David Weber <david.weber@nara.gov></david.weber@nara.gov>
Just an FYI - I had a call from Really nice, straightforward person wit is standard procedure since the 1960s for the radiologists report to be written unin the EHR. They were not interfiled with the x-rays. So the vital information contains	
Also, just a heads up, there will probably be a similar emergency destruction requhave become moldy.	lest coming for some records that were contaminated with sewage and
On Tue, Aug 3, 2021 at 9:27 AM Quoted text hidden]	wrote:
 Anne Mason (she/her), CA	
[Quoted text hidden] marianne.mason@nara.gov	
Darin Cote <darin.cote@nara.gov></darin.cote@nara.gov>	Tue, Aug 3, 2021 at 10:42 AN
To: Anne Mason <marianne.mason@nara.gov> Cc: Jack Kabrel <jack.kabrel@nara.gov>, Pamela Najar-Simpson <pamela.najar-si< th=""><td></td></pamela.najar-si<></jack.kabrel@nara.gov></marianne.mason@nara.gov>	

Thanks for the heads up - I think that's good news. As for the next request, that'll likely be mine to shepherd through.

Darin Coté Electronic Records Policy Analyst Policy and Program Support Team (ACPP) Office of the Chief Records Officer for the U.S. Government National Archives and Records Administration w 817 551.2003 (b) (6)



[Quoted text hidden]

Pamela Najar-Simpson <pamela.najar-simpson@nara.gov>

Tue, Aug 3, 2021 at 2:34 PM

To: Darin Cote <darin.cote@nara.gov>

Cc. Anne Mason <marianne.mason@nara.gov>, Jack Kabrel <jack.kabrel@nara.gov>, David Weber <david.weber@nara.gov>

Ditto for me about the good news! Not looking forward to sewage and mold---though nowhere near as much of a salvage/remediation nightmare as asbestos.

Pamela Pamela Najar-Simpson National Preservation Program Officer National Archives & Records Administration 8601 Adelphi Road, Room 3400 College Park MD 20740 tel: 301-837-0938 Cell; www.archives.gov

[Quoted text hidden]

Darin Cote <darin.cote@nara.gov>

Tue, Aug 3, 2021 at 3:02 PM

To: Pamela Najar-Simpson <pamela.najar-simpson@nara.gov> Cc: Anne Mason <marianne.mason@nara.gov>, Jack Kabrel <jack.kabrel@nara.gov>, David Weber <david.weber@nara.gov>

Agreed!

Darin Coté Electronic Records Policy Analyst Policy and Program Support Team (ACPP) Office of the Chief Records Officer for the U.S. Government National Archives and Records Administration w 817,551.2003 c





[Quoted text hidden]

@va.gov>		Mon, Aug 16, 2021 at 9:56 AM
To: Anne Mason <marianne.mascn@nara.gov>, 0,6</marianne.mascn@nara.gov>	@va.gov>	
Cc: Jack Kabrel <jack.kabrel@nara.gov>, Darin Cote <d< td=""><td>arin,cote@nara.gov>, Pamela Naiar-</td><td>Simpson <pamela.najar-simpson@nara.gov>. David Weber</pamela.najar-simpson@nara.gov></td></d<></jack.kabrel@nara.gov>	arin,cote@nara.gov>, Pamela Naiar-	Simpson <pamela.najar-simpson@nara.gov>. David Weber</pamela.najar-simpson@nara.gov>
<david.weber@nara.gov> (0)(5)</david.weber@nara.gov>	@va.gov>(®)(d)	@va.gov>, III/5
©va.gov (1/6)	@va.gov> ^{nv5}	@va.gov>

Anne/All,

Good Morning!


I am including the required items for the VA Connecticut X-Ray Request to Destroy,

Attached is the Asbestos Report and below is the snippet specific to that storage room. Also, I have included several pictures of the X-Rays and the disposition of the storage area. We were not able to get up and close to the X-Rays due to the restrictions of the mold. We will work with Contracting to get an estimate of the disposition and removal once NARA has approved.

Please let me know if there may be anything else I can provide and thank you for your assistance,


Tracy


National Archives & Records Administration Mail - Fwd: Notification and Request to Destroy Records (Medical X-Rays)



10 attachments

IMG_0046.jpg 55K





West Haven Building 1 Report Final 9-16-11.pdf

Pamela Najar-Simpson <pamela.najar-simpson@nara.gov>

Mon, Aug 16, 2021 at 11:32 AM

To: Marianne Mason <marianne mason@nara.gov>, "Kabrel, Jack" <jack.kabrel@nara.gov>, "Cote, Darin" <darin.cote@nara.gov>, "Weber, David" <david.weber@nara.gov>

Cc: Sarah Stauderman <sarah.stauderman@nara.gov>, "Olson, Allison" <allison.olson@nara.gov>

Hi all.

This is my take on the hazard report and photos, which seems to indicate the risk of asbestos contamination of the records is low/remote. However, besides mold contaminate of both the storage area and some of the records, it looks like some of the film records are damaged/deteriorated so will be difficult or impossible to use and will continue to deteriorate unless put in cold storage.

Asbestos (Based on looking at reports for past salvage projects where asbestos was suspected. You may want Bruce to take a look if the mold and damage/deterioration don't support destruction, particularly if the information is available in other records.

The asbestos testing was done on samples of suspect materials, -in this case floor tiles and coving--which scored 4 on the hazard scale and are 'good' condition. This approach/methodology is primarily used to indicate the hazard levels for when the asbestos-bearing materials are damaged or will be disturbed like during renovations. The photos show most of the loose debris has come from overhead—ceiling tiles and the like. There may have been some contamination of the leak water into the storage area, but I can't tell from the report.

This is the description of the assessment scale.

The VISN 1 hazard assessment scale 1 - 4 is a relative indicator of the risk and need for response/remediation. (1) Represents the highest priority (e.g. removal or encapsulation) where as a (4) represents the lowest priority (monitor as part of 6 month O&M program). The raling, assigned by an Asbestos Management Planner, takes into account: condition, friable vs. non - friable, accessibility, occupancy (e.g. continuous, intermittent or occasional and patients/staff/visitors), potential for air erosion, potential for vibration damage, potential for disturbance / damage (e.g. exposed and in an accessible location), and potential for water

Hope this helps with the decision.

Pamela

Pamela Najar-Simpson National Preservation Program Officer National Archives & Records Administration 8601 Adelphi Road, Roam 3400 College Park MD 20740 tel 301-837-0938 Cell: www.archives.gov


(Quoted text hidden)

10 attachments



MG_0046.jpg

IMG_0047.jpg 42K





IMG_0044.jpg 39K



IMG_0049.jpg 70K



IMG_0042.jpg 78K



IMG_0043.jpg 38K

IMG_0039.jpg 66K

IMG_0038.jpg 68K

West Haven Building 1 Report Final 9-16-11.pdf 15654K

Anne Mason <marianne.mason@nara.gov> @va.gov> Thu, Aug 19, 2021 at 6:55 AM

We'll get back to you soon with a decision or if any more questions come up as we consider the request. Thanks, Thanks [10/6] Anne Mason (she/her), CA

[Quoted text hidden] 202-430-3915 (cell) marianne.mason@nara.gov

@va.gov> To: Anne Mason <marianne.mason@nara.gov>

Thu, Aug 19, 2021 at 7:09 AM

Anne,

Excellent and thank you!

Have a great rest of your week 3

Tracy

[Quoted text hidden]

Anne Mason <marianne.mason@nara.gov>

Fri, Aug 20, 2021 at 11:23 AM

To: Pamela Najar-Simpson <pamela.najar-simpson@nara.gov>

Cc: "Kabrel, Jack" <jack.kabrel@nara.gov>, "Cote, Darin" <dain.cote@nara.gov>

The Electronic Health Record system was first scheduled in N1-015-02-003 and later superseded by DAA-0015-2015-0005

N1-015-02-003 has a really thorough description of the system and inputs between what's in the appraisal memo and the systems form the VA filled out. The appraisal memo states:

"The electronic patient medical record contains the same type of information as the hardcopy medical files. The electronic records can consist of the application for medical benefits, narrative treatment

summary, records of hospitalization, laboratory tests, x-ray images and interpretations, electrocardiograph, and other clinical and administrative records pertaining to patients.

N1-015-02-003 mentions x-rays and their interpretations in several places as inputs. DAA-0015-2015-0005 is much less descriptive of the system, but during the public comment period several commenters questioned the lesser retention of for other medical records such as 7 years for the Psychology Test Data, and the answer was that the interpretations of that data is entered into the EHR for a 75 year retention. So the intent is definitely for the reports for x-rays and similar medical records to be in the EHR and the VA is stating during scheduling & appraisal that it's happening on a consistent basis.

I added another sentence to our concur memo to the paragraph near the end where we're discussing approval for destruction. Feel free to wordsmith it or we can leave that sentence out.

[Quoted text hidden]

Anne Mason (she/her), CA

[Quoted text hidden]

(cell)

marianne mason@nara.gov

Darin Cote <darin.cote@nara.gov>

Fri, Aug 20, 2021 at 11:49 AM

To: Anne Mason <marianne.mason@nara.gov>

Cc: Pamela Najar-Simpson <pamela.najar-simpson@nara.gov>, "Kabrel, Jack" <jack.kabrel@nara.gov>

Anne,

I've made another run through the document, slicing and dicing my edits in. If you're good w/my updates (and Jack's, if any) I'd say we're good to proceed.

Best,

Darin Coté Electronic Records Policy Analyst Policy and Program Support Team (ACPP) Office of the Chief Records Officer for the U.S. Government National Archives and Records Administration w 817 551 2003 d





[Quoted text hidden]

Jack Kabrel <jack.kabrel@nara.gov>

Fri, Aug 20, 2021 at 11:54 AM

To: Darin Cote <darin.cote@nara.gov>

Cc: Anne Mason <marianne.mason@nara.gov>, Pamela Najar-Simpson <pamela.najar-simpson@nara.gov>

It looks good Anne. Enjoy your weekend everyone Jack Jack Kabrel Jack.Kabrel@nara.gov Archives Specialist National Archives and Records Administration

Permanent Records Capture Section

Cell

[Quoted text hidden]

Fri, Aug 20, 2021 at 11:59 AM

Darin Cote <darin.cote@nara.gov> To: Jack Kabrel < jack.kabrel@nara.gov>

you too Jack

Darin Coté Electronic Records Policy Analyst Policy and Program Support Team (ACPP) Office of the Chief Records Officer for the U.S. Government National Archives and Records Administration w 817.551.2003 d (D)(6)





[Quoted text hidden]

Anne Mason <marianne.mason@nara.gov>

Fri, Aug 20, 2021 at 12:23 PM

To: Darin Cote <darin.cote@nara.gov>

Cc: Pamela Najar-Simpson <pamela.najar-simpson@nara.gov>, "Kabrel, Jack" <jack.kabrel@nara.gov>

All improvements to the memo, Darin. I'll send that off to Lisa with the 2 attachments of the letters from the VA so she can start the concur process if she's good with the memo. I'll copy you all on that. Thanks!

On Fri, Aug 20, 2021 at 11:49 AM Darin Cote <darin.cote@nara.gov> wrote:

[Quoted text hidden]

Health And Safety Risks of Asbestos

Asbestos is a fibrous mineral that doesn't burn, corrode, or conduct electricity, but which combines easily with many other substances. From 1880 to 1975, asbestos fibers were mixed with asphalt, cement, paper, metals, plaster, plastics, and textiles to produce building, decorating, fireproofing, insulating, manufacturing, and soundproofing materials. Most asbestos containing material (ACM) dates from 1940-1975. Today federal law prohibits the manufacture, processing, and importation of most ACMs.

Asbestos poses risks for staff and researchers as many museums have accessioned sizable numbers of asbestos containing objects into their collections. See the list below for help in identifying likely objects. Many museum buildings have asbestos finishes, fireproofing, insulation, and other components, which when deteriorated may contaminate collections with asbestos or damage the health of staff or researchers.

The Environmental Protection Agency (EPA) estimates 3,000 historical products contain asbestos. Most ACMs are not labeled as having asbestos. ACM objects that may occur in museum collections or structures are listed in figure 1.

Asbestos as a Health and Safety Risk

Asbestos is relatively safe until it is crushed, cut, filed, scraped, or otherwise released from binding materials. Asbestos that can be crushed by hand pressure alone is called friable. When crushed, ACMs break up into fine abrasive fibers that are often invisible to the eye, rather than turning to dust as other minerals do. Humans are most at

risk when they breathe in asbestos fibers. Handling asbestos or even eating in asbestos-contaminated areas can pose risks as well. Individuals exposed to asbestos should have a medical examination that includes a medical history, breathing capacity test and chest x-ray in order to detect problems early. Exposed asbestos particles can penetrate and remain in lungs and airways leading to cancers in the esophagus, larynx, lungs, oral cavity, stomach, colon and kidneys. Because asbestos fibers remain in the body, each exposure increases the likelihood of developing an asbestos-related disease. Asbestos-related diseases may not appear until several decades after exposure.

Figure 1. Sources of asbestos in collections

appliances asphalt felt, sheeting, shingles, and tile brake shoes and clutch pads carpet padding ceiling panels and tiles cement pipes and sheets chalkboards fire curtains, doors, and blankets floor tiles (linoleum and vinyl) furnace, gas fireplace, and oven gaskets and packing geological specimens insulation for buildings, ducts and pipes mining equipment and paraphernalia paper such as aircell cardboard patching and spackling compounds plaster wrapping materials roofing materials sealants and sprays for ceilings sealants and finishes for floors and walls taping compounds textiles (clothing, hot pads, ironing board covers) textured paints wall boards, tiles, and textured finishes

Lung cancer poses the greatest single health risk for those exposed to asbestos fibers. According to the EPA, smokers who are exposed to asbestos have a lung cancer risk that is 50-90 times greater than non-smokers with no asbestos exposure. Asbestosis, a serious, chronic non-cancerous scarring of the lungs that has no effective treatment, is another major risk. Skin rash is an indicator of asbestos exposure by handling.

History of Asbestos Use in the United States

Asbestos was first used in the United States in the early 1880's, to insulate equipment such as steam engines. Widespread asbestos use was rare until the 1940-1975 era, when asbestos was widely used in new and renovated buildings, particularly for public buildings and schools. After surveying 3.6 million public and commercial buildings in 1988, the EPA found friable asbestos in 20% of the structures surveyed. Between 1940 and 1980, the EPA estimates that 27 million Americans had significant occupational exposure to asbestos.

Asbestos Exposure Methods in Collections

Staff or researchers who do not wear proper protective gear while working with asbestoscontaining objects may experience dangerous exposure to asbestos. Staff or researchers working in asbestos contaminated office, storage, or research spaces may also suffer from asbestos exposure. Finally, staff or researchers working on collections currently or previously housed in asbestos contaminated spaces may also be dangerously exposed to asbestos.

The most dangerous spaces are those where the ACMs have been disturbed, damaged, or otherwise stirred up or where no sealant or enclosure exists around the ACM. The most dangerous time is during demolition, renovation, or repair of the space, although aggressive cleaning also poses risks. ACM in a heavy traffic area that is often disturbed is more likely to release fibers than ACM in an undisturbed area. Attics and basements frequently contain leaking or damaged asbestos containing materials

such as ceiling or floor tiles, decorative finishes, fire or sound-proofing materials, insulation, shingles, or wallboard.

Damaged ACMs release asbestos particles into the air that are 1,200 times thinner than a human hair. These small and light particles remain in the air for a long time. Asbestos in the air can rain down on collections coating them with fibers. As staff touch contaminated collections, they stir the fibers into the air and onto their clothing and hair. People may ingest asbestos if they eat in areas where there are fibers in the air. Families of exposed staff may inhale asbestos fibers from the exposed person's clothing if precautions aren't taken.

Asbestos exposure levels will vary according to:

- concentration of fibers in the air
- duration of exposure
- · worker's breathing rate
- weather conditions or air circulation levels
- type of protective devices the worker wears

The EPA has not set a safe level for asbestos exposure in the air, by ingestion, or by handling, although the Occupational Safety and Health Administration (OSHA) indicates that a permissible exposure limit is 0.1 fibers per cubic centimeter for an 8-hour time weighted average. Since asbestos damage is cumulative, avoid exposure.

Protection from Asbestos

Don't work in or place collections in spaces dating from pre-1975 that may contain significant or damaged ACMs, such as:

- spaces with exposed insulation on walls, ceilings, pipes, or wiring
- spaces with damaged wallboard, floor and ceiling tiles, cement, or textured finishes
- spaces undergoing renovation, repair, or energetic cleaning
- spaces near pre-1975 building demolition sites

Don't provide asbestos-contaminated collections, to researchers or staff without taking appropriate precautions. Do not allow staff or researchers to work in asbestos-contaminated spaces.

Avoid entering spaces with disturbed ACMs. If you must enter an asbestos-contaminated space, work with asbestos-contaminated collections, or work with asbestos-containing objects, wear protective clothing, neoprene gloves, and a rated breathing apparatus with a HEPA filter, such as a P100 filter, that is at least 99.97% efficient with particles down to .3 microns. Fit test your respirator. Limit asbestos exposure to the shortest period possible. Don't attempt to do asbestos mitigation without special training. If collections have been contaminated with asbestos, contact a conservator equipped and trained to deal with asbestos mitigation.

Identification of Asbestos

Until a product is tested, it is best to assume that the product contains asbestos, unless the label or the manufacturer verifies that it does not.

Suspect any pre-1975 composite boards, finishes, flooring, tiling, insulation, and cement materials in a building or as architectural fragments in collections. There are two ways to identify asbestos:

- instrumental analysis, such as microscopy (described in figure 2)
- verification with the manufacturer.

Testing should be done by an appropriate accredited laboratory. EPA Regional Offices can

provide information about laboratories that test for asbestos.

Only trained professionals should sample asbestos. If you must take a sample of asbestos, do the following:

- wear protective clothing, goggles, neoprene gloves, and a fit-tested respirator
- use a fine water mist, such as a plant mister, in the area prior to taking the sample to reduce the amount of asbestos in the air
- · disturb the area as little as possible
- collect materials with a small film canister or vial that has a lid
- seal the lid after collecting a specimen, then wipe the outside with a damp cloth
- label the container with the building, room, and area identification information
- send the sample to a designated testing laboratory

Asbestos Management

Don't try to remove or mitigate asbestos by yourself. Only individuals trained in asbestos compliance can remove or disturb asbestos. To manage a space with ACMs:

- keep ACMs in good condition by avoiding heavy activity in the area
- spray undamaged ACMs with appropriate sealants
- repair damaged ACMs by enclosing them as suggested by OSHA and EPA
- get professional help before attempting to remove ACMs

Type of Microscopy	Sample Type	Information Obtained	
Phase Contrast Microscopy (PCM)	Bulk	Percentage of asbestos in the tested materials. Note: This test is EPA required for all suspect materials.	
Polarized Light Microscopy (PLM)	Bulk	Whether or not the sample is asbestos. Percentage of asbestos in the tested materials.	
Transmission Electron Microscopy (TEM)	Small sample of fibers	Whether or not the sample is asbestos. Note: This test does not provide accurate percentage of asbestos.	

Figure 2. Types of microscopic analysis used to identify asbestos

The goal is to keep ACMs in good repair and avoid releasing asbestos fibers. Asbestoscontaminated rooms must be repaired or have their ACMs removed by trained mitigation professionals, not curatorial staff. Contact the EPA for names of contractors. If you have asbestos-contaminated collections, trained conservators experienced and qualified to deal with asbestos mitigation should clean them.

Sources of Help

Contact your safety officer. Both the EPA and OSHA have linked regulations relating to asbestos safety. You can obtain more information about asbestos by calling the EPA Toxic Substances Control Act (TSCA) Hotline, (202) 554-1404. The EPA Public Information Center can send you information on EPA regulations at (202) 382-2080 or (202) 475-7751. For copies of asbestos-related regulations, contact the Office of the Federal Register at (202) 382-5475. Finally, the EPA has an Asbestos Ombudsman to provide information on the handling and abatement of asbestos at (800) 368-5888 or (703) 557-1938.

Web-based Resources:

OSHA Asbestos Web Page: http://www.osha-slc.gov/SLTC/asbestos/

Environmental Protection Agency Asbestos Web Page: http://www.epa.gov/earth1r6/6pd/pd-t/asbmatl.htm

National Voluntary Laboratory Accreditation Program list of Certified Asbestos Labs: http://ts.nist.gov/ts/htdocs/210/214/214.htm

Notes

1. For a list of asbestos testing laboratories accredited by the National Institute of Standards and Technology (NIST) see their Web site at http://ts.nist.gov/ts/htdocs/210/214/scopes/plmtm.htm

Bibliography

EPA. Managing Asbestos In-Place: A Building Owner's Guide to Operations and Maintenance Programs for Asbestos-Containing Materials. Washington, D.C.: Environmental Protection Agency, n.d.

National Institute of Building Sciences. Guidance Manual, Asbestos Operations & Maintenance Work Practices, 2d ed. Washington, D.C.: National Institute of Building Sciences, 1996.


Asbestos Abatement and Management in Buildings, Model Guide Specifications, 3d ed. Washington, D.C.: National Institute of Building Sciences, 1996.

The author thanks the United States Environmental Protection Agency, Office of Air Quality Planning and Standards Stationary Source Compliance Division.

Diane Vogt-O'Connor Senior Archivist Museum Management Program, NPS Washington, DC

The Conserve O Gram series is published as a reference on collections management and curatorial issues. Mention of a product, a manufacturer, or a supplier by name in this publication does not constitute an endorsement of that product or supplier by the National Park Service. Sources named are not all inclusive. It is suggested that readers also seek alternative product and vendor information in order to assess the full range of available supplies and equipment. The series is distributed to all NPS units


and is available to non-NPS institutions and interested individuals b subscription through the Superintendent of Documents, U.S. Governmer Printing Office, Washington, DC 20402; FAX (202) 512-2250 or on the Web at http://www.cr.nps.gov/csd. For further information an guidance concerning any of the topics or procedures addressed in the series, contact NPS Museum Management Program, 1849 C Street NV (NC 230), Washington, DC 20240; (202) 343-8142.





















Department of Veterans Affairs

Memorandum

Date: January 31, 2020

From: Records Management Officer, VA Connecticut Healthcare System

Thru: Medical Center Director, VA Connecticut West Haven Campus

Subj: Report on Accidental Destruction of Medical X-Rays by Asbestos and Mold Contamination

To: VHA Record Manager

- This report is made in accordance with the National Archives and Records Administration (NARA) Regulation Titel 36, Chapter XII, Subchapter B Part 1230, subject above. Federal agencies are required to report to NARA any unlawful or accidental removal, defacing, alteration, or destruction of records.
- 2. The VA Connecticut Healthcare System, West Haven Campus, identified that the Diagnostic Radiology Service Line had a storage location in the Sub Basement containing roughly 30K Patient X-ray Jackets which included, X-rays, CT, MRI and ultrasound scans dating back before 2003. This practice lead to the accidental destruction of these files by contamination due to asbestos and mold.
- The following information provides specific details concerning the damaged X-Ray records:
 - (a) <u>Records Description and Volume:</u> Patient X-ray jackets with a mixture of X-rays, ultrasounds, CT scans and MRI scans completed prior to FY 2003 that should have been destroyed 5 years after the dates of the last exposure or 10 years after Veteran's separation from military service, per RCS 10-1, 7200.6.
 a. The number of patient files destroyed is estimated to be over 30K.
 - (b) Office of Origin: The Diagnostic Radiology Service maintained the X-ray jackets of VA Connecticut Veterans on file at the West Haven Campus.
 - (c) <u>Statement of the Exact Circumstances Surrounding the Alienation, Defacing, or Destruction of the Records:</u> The area the X-rays are contained in are beneath the piping and ducts for the heating and cooling systems for the hospital which over time has leaked and created mold. The walls, flooring and ceiling tiles all contain asbestos due to the era they were constructed. With the mix of the two contaminates, the X-ray became contaminated and have now been damaged.

- (d) Action Taken to Salvage, Retrieve, or Reconstruct the Records: Due to the asbestos and mold contamination, there has been no way to salvage, retrieve or reconstruct the Patient X-ray Jackets. The subground area where the records are located is not accessable.
- (e) Action Taken to Correct Problem: To ensure that X-rays are not contaminated with asbestos or mold in the future, all CT/MRI and X-rays are currently in an electroinc format and are not on film.

4. If you	have any questions,	a member of your staff r	nav contact
Conne	ecticut Healthcare Sy	a member of your staff r	at 860-666-6951
(b)(6)			
			•
Concur / Do I	Not Concur		•
(0)(6)			
(0)(6)			